

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of: )  
TATSUO FURUKAWA ) : Examiner: Juanita D. Stephens  
Appln. No.: 10/555,304 ) : Art Unit: 2853  
Filed: November 2, 2005 ) : Conf. No.: 7687  
For: INK-JET PRINthead SUBSTRATE, )  
DRIVING CONTROL METHOD, )  
INK-JET PRINthead AND INK-JET )  
PRINTING APPARATUS )  
U.S. Patent No.: 7,267,429 B2 )  
Issued: September 11, 2007 : February 4, 2008

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION  
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form is attached.

The amount of \$100.00 to cover the statutory fee for such Certificate of Correction is being paid concurrently; please charge any deficiency in this fee, and credit any overpayment, to Deposit Account 50-3939.

Patentee's undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

/ Elizabeth F. Holowacz /  
Elizabeth F. Holowacz  
Attorney for Patentee  
Registration No. 42,667

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
Facsimile: (212) 218-2200

1945242v1

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

Staple  
Here  
Only!

PRINTER'S TRIM LINE

PATENT NO. : 7,267,429 B2

DATED : September 11, 2007

INVENTOR(S) : TATSUO FURUKAWA

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 3**

Line 7, "printhead-takes" should read --printhead takes--.

**COLUMN 4**

Line 59, "and" should be deleted; and

Line 61, "circuit." should read --circuit;--.

**COLUMN 5**

Line 14, "made have" should read --may have--.

**COLUMN 6**

Line 27, "timing" should read --timing,--;

Line 29, "had" should read --made--;

Line 30, "described" should read --describe--; and

Line 44, "motor 1709" should read --motor--.

**COLUMN 7**

Line 26, "channels" should read --channel--; and

Line 44, "called-a" should read --called a--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 7,267,429 B2

No. of add'l. copies  
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

Staple  
Here  
Only!

PRINTER'S TRIM LINE

PATENT NO. : 7,267,429 B2

DATED : September 11, 2007

INVENTOR(S) : TATSUO FURUKAWA

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 9**

Line 39, close up right margin; and

Line 40, close up left margin.

**COLUMN 10**

Line 38, "convening" should read --converting--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 7,267,429 B2

No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

1945242v1

